

NASCAR Cup Series					
Date	Track	Team/Member	Level	Infraction	Penalty/Remarks
7/21/2021 (post-race inspection)	New Hampshire	No. 9	L1	Sections 20.6.1.e: Engine Assembly Note: When the long block is sealed the engine must be used in the same vehicle number the next time it is used.	Crew chief (Alan Gustafson) has been fined \$50,000 and director of track engine support (Scott Maxim) has been suspended from the next NASCAR Cup Series Championship Points Event. Team has been assessed with the loss of 25 owner points and 25 driver points.
7/21/2021 (post-race inspection)	New Hampshire	No. 48	L1	Sections 20.6.1.e: Engine Assembly Note: When the long block is sealed the engine must be used in the same vehicle number the next time it is used.	Crew chief (Greg Ives) has been fined \$50,000 and executive vice president and general manager (Jeff Andrews) has been suspended from the next NASCAR Cup Series Championship Points Event. Team has been assessed with the loss of 25 owner points and 25 driver points. <i>(Note: Engine seal credit will not be applied)</i>