



Infraction Sheet

Homestead-Miami Speedway

Ford EcoBoost 400



Provided by NASCAR Statistics - Sun, November 20, 2016 @ 06:17 PM Central

No	Lap	Infraction	Flag	Penalty	Lap Assessed	Notes
48		Pre-Race to the rear	W	tail end		unapproved body modification
21	27	Pitting before pit road is open	Y	tail end	31	
21	27	Too many crewmember(s) in contact with pit service area	Y	tail end	31	
27	29	Crewmember(s) over the wall too soon	Y	tail end	31	
88	81	Too many crewmember(s) in contact with pit service area	Y	tail end	85	
43	83	Too many crewmember(s) in contact with pit service area	Y	tail end	85	
47	120	Outside half of the pit box tire violation/Team member not in contact with the outside tires	G	pass thru	124	
49	152	Speed-Entering pits	G	pass thru	156	
21	207	Pitting before pit road is open	Y	tail end	212	
21	207	Too many crewmember(s) in contact with pit service area	Y	tail end	212	
21	207	Tossing or throwing the fuel filler/overflow containers/equipment	Y	tail end	212	
21	211	Too many crewmember(s) in contact with pit service area	Y	tail end	212	
32	253	Pitting before pit road is open	Y	tail end	257	
95	258	Pitting before pit road is open	Y	tail end		garage
24	258	Pitting before pit road is open	Y	tail end	262	
13	258	Pitting before pit road is open	Y	tail end	262	
31	258	Pitting before pit road is open	Y	tail end	262	
95	258	Too many crewmember(s) in contact with pit service area	Y	tail end		garage
24	258	Too many crewmember(s) in contact with pit service area	Y	tail end	262	
31	258	Too many crewmember(s) in contact with pit service area	Y	tail end	262	
13	258	Too many crewmember(s) in contact with pit service area	Y	tail end	262	
31	263	Pitting before pit road is open	Y	tail end		garage
17	263	Pitting before pit road is open	Y	tail end		garage