

NASCAR Cup Series					
Date	Track	Team/Member	Level	Infraction	Penalty/Remarks
4/11/2021 (post-race inspection)	Martinsville	No. 5	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Cliff Daniels) has been fined \$10,000.
4/11/2021 (post-race inspection)	Martinsville	No. 14	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (John Klausmeier) has been fined \$10,000.
4/11/2021 (post-race inspection)	Martinsville	No. 47	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Brian Pattie) has been fined \$10,000.
4/10/2021 (pre-race inspection)	Martinsville	No. 99	L1	Section 20.17.2.1b: Overall vehicle weight <i>Note: Improperly mounted ballast</i>	Team has been assessed with the loss of 10 owner points and 10 driver points.

NASCAR Xfinity Series					
Date	Track	Team/Member	Level	Infraction	Penalty/Remarks
4/11/2021 (post-race inspection)	Martinsville	No. 19	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Jeff Meendering) has been fined \$5,000.
4/11/2021 (post-race inspection)	Martinsville	No. 23	Safety	Sections 12.5.2.7.4: Loss or separation of an improperly installed rear axle from the vehicle <i>Note: Loss of axle during the event.</i>	Crew member (Brian Graham) is suspended from the next NASCAR Xfinity Series event.

NASCAR					
Date	Track	Team/Member	Level	Infraction	Penalty/Remarks
4/13/2021	N/A	Kurt Butcher	Behavioral (SAP)	Sections 12.1 & 19	Indefinite suspension from NASCAR